
**AMMRC TR 76-35** 





## SECONDARY DAMAGE TO AIRCRAFT BY RICOCHETED SMALL ARMS PROJECTILES AND FRAGMENTS

STUARTEV. ARNOLD AND RUSSELL G. HARDY

MATERIALS APPLICATION DIVISION

November 1976

Pil Rep 28 1916 Lill

COPY

Approved for public release; distribution unlimited.

ARMY MATERIALS AND MECHANICS RESEARCH CENTER Watertown, Massachusetts 02172

BC FILE

# Best Available Copy

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

Mention of any trade names or manufacturers in this report shall not be construed as advertising nor as an official indorsement or approval of such products or companies by the United States Government.

**DISPOSITION INSTRUCTIONS** 

Destroy this report when it is no longer needed.

Do not return it to the originator.

	GE READ INSTRUCTIONS BEFORE COMPLETING FORM
	OVT ACCESSION NO. 3. RECIPIENT'S CATALOG NUMBER
AMMRC-TR-76-35	
I. TITLE (and Sublitia)	S-TYPE OF REPORT & PERIOD COVE
SECONDARY DAMAGE TO AIRCRAFT BY RIC	COCHETED/ (9)
SMALL ARMS PROJECTILES AND FRAGMEN	
	FERFORMING ORG. REPORT NUMBE
7. AUTHOR(a)	S. CANTRACT OR COANT WINDER
	GONTRACTOR GRANT NUMBER(s)
Stuart V. Arnold Russell G./Ha	rdy ( )
Stuart V. Armord Law Russerr G. Ha	Tuy
PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TAREA & WORK UNIT NUMBERS
Army Materials and Mechanics Research	ch Center D/A Project: 1T162105AH84
Watertown, Massachusetts 02172	AMCMS Code: 612105.11.H84
DRXMR-K  1. CONTROLLING OFFICE NAME AND ADDRESS	.12. REPORT DATE
U.S. Army Materiel Development and	
Readiness Command, Alexandria, Vir	ginia 22333 13 NOTISER OF PAGES
	19 (2) 25
4. MONITORING AGENCY NAME & ADDRESS(II dillerent tron	n Controlling Office) 15. SECURITY CLASS. (of his report)
	Unclassified
	15a, DECLASSIFICATION/DOWNGRADIN
	SCHEDULE
6. DISTRIBUTION STATEMENT (of this Report)	
Approved for public release; distrib	oution unlimited.
The state of the s	
, constant and passed and and and and and and and and and an	
	lack 20, if different from Report)
	luck 20, if different from Report)
	lack 20, il dillerent from Report)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bi	luck 20, il dillerent trom Report)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bi	lack 20, if different from Report)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bi	lack 20, il dillerent from Report)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bi	lock 20, if different from Report)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bi	
17. DISTRIBUTION STATEMENT (of the abetract entered in Bi	
17. DISTRIBUTION STATEMENT (of the abstract entered in Bit 18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side II necessary and identification of the abstract of the abstract of the abstract on the abstract of the abstract of the abstract of the abstract on the abstract of the abstract on the abstract of the abstract on	
17. DISTRIBUTION STATEMENT (of the abstract entered in Billion Supplementary notes  18. Supplementary notes  19. Key words (Continue on reverse side II necessary and ide Aircraft vulnerability Tita Terminal ballistics	ontify by block number)
17. DISTRIBUTION STATEMENT (of the abstract entered in Bit 18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side II necessary and identification of the abstract on the abstract of the abstract on the abstract of the abstract ontered in Bit 19.  19. KEY WORDS (Continue on reverse side II necessary and identification).  Tital	ontify by block number)
17. DISTRIBUTION STATEMENT (of the abstract entered in Billion Supplementary notes  18. Supplementary notes  19. Key words (Continue on reverse side II necessary and ide Aircraft vulnerability Tita Terminal ballistics	ontily by block number)

(SEE REVERSE SIDE)

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)


Block No. 20

ABSTRACT

Under certain conditions of oblique impact against aircraft structures, small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber .30 AP M2 and 7.62-mm ball M59 projectiles striking 0.375-inch-thick 2024-T351 aluminum and 0.25-inch-thick Ti-6Al-4V alloy plates over ranges of obliquity and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.

### CONTENTS

Pa	age
INTRODUCTION	1
EFFECT OF OBLIQUITY ON ARMOR DESIGN	1
BALLISTIC BEHAVIOR OF AIRCRAFT STRUCTURE	2
TEST PROCEDURE	
Materials	2
Projectiles	2
Fixture	2
Test Methods	4
DISCUSSION	
Terminal Ballistics of Caliber .30 AP M2 Projectiles Impacting Obliquely	4
Secondary Damage by Fragments	8
Terminal Ballistics of 7.62-MM Ball M59 Projectiles	Ŭ
	10
Aircraft Design for Reduced Vulnerability	12
CONCLUSIONS	13
ACKNOWLEDGMENT	14
APPENDIX. STACK PENETRATION BY FRAGMENT-SIMULATING PROJECTILES	15



#### INTRODUCTION

Obliquity of impact is a factor affecting vulnerability of structural components to hits by projectiles from small arms, machine guns, and automatic cannon. If obliquity is sufficiently high, the projectiles will ricochet, possibly to strike other components or personnel. Depending upon the nature of and interaction between a metal component and the projectile, the component may eject plugs or back-spall and the projectile may shatter into a number of fragments. This report covers certain experiments designed to assess the damage potential of such secondary particles. The objective of this research was to provide information which could be used for design of aircraft possessing increased survivability against the above threats.

#### EFFECT OF OBLIQUITY ON ARMOR DESIGN

Under circumstances which restrict the direction of attack by projectile threats, considerable ravings in weight can be realized by inclining protective armor plate at an angle oblique\* to that direction. The glacis plates of tanks, which are attacked predominantly by projectiles in near-horizontal trajectories from a frontal direction, are inclined in such fashion for this very reason. Ballistic data readily demonstrate that, for a given areal density of armor, the ballistic limit increases with obliquity. Analysis based on these data serves to indicate that disposition of armor plate at 60° obliquity can result in savings exceeding 35% of the weight which would have been required for protection had the plate been positioned perpendicular to the direction of attack, i.e., at 0° obliquity.† Where high obliquities are not compatible with design requirements, benefits of more modest obliquities in the 30° to 40° range remain considerable (see Figure 1).




Figure 1. Reduction in armor weight\* as a function of obliquity.

<sup>\*</sup>Weight necessary to protect against cal. .50 AP M2 projectiles through a solid angle of incident fire at 500 yards range.

<sup>\*</sup>The angle of obliquity is defined by the shot line and a perpendicular to the plates at point of impact.

† ARNOLD, S. V. Ballistic Behavior of Armor Under Oblique Impact. Army Materials and Mechanics Research Center, AMMRC Memorandum, 6 March 1975.

MASCIANICA, F. S. Ballistic Technology of Lightweight Armor - 1976 (U). Army Materials and Mechanics Research Center, AMMRC TR 76-15, May 1976 (Confidential Report).

#### BALLISTIC BEHAVIOR OF AIRCRAFT STRUCTURE

Whereas use of parasitic\* metallic armor in aircraft is severely limited by the penalty which its weight imposes on performance, some integral armors are more attractive. Aluminum and titanium alloys have well-documented capabilities as armor materials. Obviously, structural members made from these materials behave under ballistic attack in much the same fashion as armor, both in withstanding projectile impact and in shielding other components in the line of fire. Again, obliquity of impact degrades ability for penetration and may result in projectile ricochet. Indeed, if ricochet occurs, the damage potential of ricocheted projectiles (or fragments thereof) varies with obliquity. Vulnerability of components and personnel to such secondary effects can be estimated if direction and energy of ricocheted particles are known.

#### TEST PROCEDURE

#### Materials

Panels for ballistic test were sheared from 0.375-inch-thick plate of aluminum 2024 alloy in the T351 condition and from 0.25-inch-thick plate of Ti-6A1-4V alloy in the mill-annealed condition. Areal densities of these plates (intended to be roughly equivalent) were 5.4 and 5.76 pounds per square foot. Square sections were also cut from fiber board to be used in stacks for catching ricocheted projectiles and fragments. The fiber boards, identified as Conwed Rock-Face firerated acoustical ceiling panel, were 0.645 inch thick.

#### **Projectiles**

The caliber .30 AP M2 round was used for studying terminal ballistics of armor-piercing small arms projectiles. This round has a 166-grain projectile consisting of a copper alloy jacket surrounding an 81-grain hardened steel core.

The 7.62-mm ball M59 round (intended primarily for use against personnel and soft targets) was selected for studying terminal ballistics of a projectile the core of which deforms, rather than fragments. This round has a 150-grain projectile consisting of a copper alloy jacket surrounding a 55-grain soft steel core.

Several fragment-simulating projectiles (FSP) were also employed with calibers and weights as follow: cal. .10 (1.35 grains), cal. .15 (5.85 grains), cal. .22 (17 grains), cal. .30 (44 grains). These projectiles are roughly cylindrical in shape, fashioned from steel and heat treated to a hardness of Rockwell C 30 (see Appendix).

#### Fixture

A test fixture was constructed of structural channel section for holding (a) the plate to be tested, and (b) a stack of panels positioned to catch projectiles or fragments ricocheting from the plate surface. The fixture and test setup are shown in Figures 2 and 3.

<sup>\*&</sup>quot;Parasitic" armor performs solely in a protective role, as differentiated from "integral" armor which serves simultaneously in protective and structural capacities.




Figure 2. Test setup for ricochet experiment. A cal. .30 AP M2 projectile (following a trajectory in line with the ruler) struck the Ti-6Al-4V plate at 55° obliquity and fragmented. The ricocheting fragments were caught in the upper left corner of the stack (area 10).

19-066-1663/AMC-75




Figure 3. Ricochet setup showing plate impact points 9 and 10 and corresponding areas (below) where ricocheting fragments entered the stack. Note perforations indicating spray of fine fragments close to the plate surface (see arrow), also larger and separate perforations from heavier fragments.

19-066-1662/AMC-75

#### Test Methods

In the first experiment caliber .30 AP M2 projectiles were fired at 1800, 2200, and 2600 fps velocities to impact the test plate at high obliquities. (These velocities correspond respectively to ranges of 500, 275, and 75 yards for this projectile using the standard charge of powder.) Obliquities were successively reduced until penetration occurred at each velocity. Ricocheted projectiles or fragments were caught in a stack of square panel sections stationed beyond the point of impact in a plane perpendicular to that of the plate (see Figure 2). By changing the point of impact and rotating the stack 180°, ricochet from succeeding shots could be kept separate within the stack. By careful disassembly of the stack, entrapped projectiles/fragments were recovered, their positions relative to the point of impact recorded, and their weight measured. From these data ricochet angle and distance of fragment penetration were calculated. Behavior of fragments other than steel was not analyzed. Steel fragments smaller than 3 grains are not reported herein.

In a second experiment the stack was positioned immediately behind the test plate to entrap projectiles which had completely penetrated the plate. Stack disassembly and recovery of projectiles/fragments enabled measurement of weights and calculation of penetration distances.

In a third experiment various fragment-simulating projectiles were fired into stacks at zero obliquity over a range of velocities. Stack disassembly and projectile recovery was used to establish velocity/penetration relations for the various weights of FSP (see Appendix).

In a fourth experiment 7.62-mm ball M59 projectiles were fired at selected velocities to impact obliquely and to ricochet into a catching stack, as in the first experiment.

#### DISCUSSION

Terminal Ballistics of Caliber .30 AP M2 Projectiles Impacting Obliquely

Terminal ballistic data are presented in Table 1 for 0.375-inch-thick 2024-T351 and 0.25-inch-thick Ti-6A1-4V plate, both under oblique impact by caliber .30 AP M2 projectiles. Individual shots are itemized to facilitate comparison. Items are listed in order of increasing obliquity and in order of increasing striking velocity within each obliquity grouping. Criterion for complete penetration was perforation of a 0.020-inch-thick aluminum witness sheet positioned 6 inches behind and parallel to the target plate. Whereas distance of fragment penetration through stack panel material was calculated from direct measurements, velocities are estimated on the assumption that projectile fragments behave as do FSP (see Appendix).

Items 1, 2, 4, 5, and 9 present data which give some insight to damage potential of fragments formed which caliber .30 AP M2 projectiles completely penetrate 0.375-inch-thick 2024-T351 plate.

Table 1. FERMINAL BALLISTICS OF CALIBER .30 AP M2 PROJECTILES VERSUS 0.375-INCH-THICK 2024-T351 PLATE (5.4 PSF)

Item	Obliquity (degrees)	Velocity (†ps)	Extent of Plate Penetration	Weight	Ricochet	Ricochet Stack Penetration (inches)	Ricochet Velocity* (fps)	Behind-Plate Stack Penetration (inches)	Behind-Plate Velocity* (fps)	Remarks
1	30 30	1847 1847	Complete Complete	35.5 43.3	NA NA	NA NA	NA NA	7.2 5.9	1540 1150	Nose fragment Base fragment
2	40	1674	Complete	35.0	NA	NA	NA	5.2	1040	Nose recovered, base passed through stack
3	40	1818	Complete	-	-	-	-	-	-	Unrecovered.
4	40 40	1887 1887	Complete Complete	7.6 27.8	NA NA	na Na	NA NA	4.8 4.8	1000 1000	Base and smaller fragment traveled together, nose passed through stack
5	40	2112	Complete	36.8	NA	NA	NA	8.6	1890	Base fragments, nose lost
6	50 50	1799 1799	Partial Partial	36.2 43.1	21 17	5.3 5.8	1100 1150	NA NA	NA NA	Nose fragment Base fragment
7	50	2104	Partia1	•	-	-	-	-	-	Unrecovered*
8	50	2222	Complete	-	-	-	•	-	-	Unrecovered:
9	50	2569	Complete	-	-	-	-	7.8+	1400+	Projectile passed through stack
10 10 10	60 60 60	1815 1815 1815	Partial	6.6 27.6 31.6	16 16 16	7.9 7.9 7.2	1750 1750 1500	AA 	NA 	Base and center fragments which traveled together Nose fragment
11	60	1825		36.4	20	7.2	1520	ľ		Base fragment
12 12	60 60	2208 2208		31.3 47.5	16 18	7.8 7.1	1800 1350			Nose fragment Base fragment
13 13	60 60	2632 2632		23.0 31.4	27 22	6.2 8.4	1450 1950			Center fragment Nose fragment
14 14 14	70 70 70	2632 2632 2632		7.0 29.2 36.5	11 11 13	8.4 9.0 9.6	2600+ 2180 2150			Center fragment Nose fragment Base fragment

\*Velocity estimated on basis of stack penetration by fragment-simulating projectiles striking at measured velocities.

\*Ricocheted projectiles/fragments were not recovered during behind-the-plate studies; projectiles/fragments completely penetrating the plate were not recovered during ricochet studies.

Even at velocities corresponding to ranges of 500 yards and further, complete penetration occurred at obliquities of 30 and 40 degrees. No projectile was recovered intact after complete penetration. The steel core commonly broke into two large fragments corresponding to the nose and base portions, which accounted for nearly all the 81-grain total weight. These large fragments achieved pack penetration sufficient to demonstrate considerable potential for secondary damage. The copper jacket which surrounds the core also passed through the plate and penetrated the stack as highly irregular pieces, which generally traveled shorter distances than the more compact core fragments. Commonly, the projectile pushed out a plug from the aluminum plate which traveled a short distance into the stack.

When obliquity was increased to 50 degrees, the projectile failed to penetrate at a velocity equivalent to 500 yards range (see Item 7) but ricocheted, the core again breaking into two large fragments. At a velocity corresponding to 275 yards complete penetration resulted (see Item 8).

At 60° obliquity, ricochet occurred at all test velocities, i.e., over the spectrum of ranges to be encountered in service (see Items 10 to 13). Many of the larger ricocheted fragments retained nearly all of their striking velocity, i.e., they retained potential for inflicting serious damage to other parts of adjoining structure or components upon which they might impinge.

No reliable correlations between angle of ricochet and striking conditions were noticeable for Items 6, 10 to 14, possibly excepting the fact that lowest angle occurred with highest obliquity.

Table 2. TERMINAL BALLISTICS OF CALIBER .30 AP M2 PROJECTILES VERSUS 0.25-INCH-THICK Ti-6A1-4V PLATE (5.76 PSF)

Item	Obliquity (degrees)	Velocity (fps)	Extent of Plate Penetration	Weight	Ricochet		Ricochet Velocity* (fps)	Behind-Plate Stack Penetration (inches)	Behind-Plate Velocity: (fps)	Remarks
15	0	1789	Complete	•	NA	NA	NA	7.8+	-	Projectile passed through stack
16	30	1707	Partial	-	•	•	•	•	-	Unrecovered+
17	30	2170	Complete	7.8	NA	NA	NA	3.2	990	Center fragment
18 18	30 30	2298 2298	Complete Complete	6.3 27.0	NA NA	na Na	NA NA	5 0 4.3	1760 950	Center fragment Base fragment
19 19	30 30	2595 2595	Complete Complete	6.0 9.4	NA NA	na Na	NA NA	2.0 2.0	<800 <800	These are several Ti fragments found together
20	40	1748	Complete	-	•	-	-	-	- }	Projectile did not pene- trate; slight back-spall
21	40	1872	Complete	-	-	•	-	-	- )	
22	40	2390	Partial	-	-	-	-	-	-	Back of plate cracked
23 23	40 40	2560 2560	Complete Complete	8.5 10.9	NA NA	NA NA	na Na	4.6 5.4	1440 1640	Considerable back-spall Considerable back-spall
24 24 24 24 24	45 45 45 45 45	1790 1790 1790 1790 1790	Partial	4.6 8.5 11.5 13.2 21.7	32 23 23 24 23	0.6 1.4 0.7 2.2 0.7	<800 <800 <800 <800 <800	NA 	NA 	Center fragment Center fragment Center fragment Center fragment Base fragment
25 25 25	50 50 50	1776 1776 1776		4.1 9.3 59.5	13 21 18	4.0 4.2 2.7	1490 1150 <800			Center fragment Nose fragment Base fragment
26 26	50 50	1802 1802	]	18.5 39.0	21 0	6.6 6.2	1730 1230			Nose fragment Base fragment
27 27 27	50 50 50	2163 2163 2163	ļ	6.0 16.0 39.2	10 21 20	3.6 6.6 4.5	1100 1800 950			Center fragment Nose fragment Base fragment
28	50	2244	Complete	22.5	10	7.9	2100	-	-	Projectile did not pene- trate; slight back-spall
29 29 29	55 55 55	2187 2187 2187	Partial	5.9 20.8 46.5	13 15 18	3.0 7.0 3.0	850 1180 <800	NA 	NA 	Center fragment Nose fragment Base fragment
30 30 30 30	55 55 55 55	2633 2633 2633 2633		4.9 5.7 21.0 43.5	1 17 12 33	4.2 5.1 7.7 2.8	1500 1860 2050 <800			Back of plate cracked Center fragment Nose fragment Base fragment
31	60	1795	'	26.5	11	7.9	1900			Nose fragment
32	60	1820		23.9	11	6.9	1700			Nose fragment
33 33 33	60 60 60	2202 2202 2202		3.7 8.2 33.0	12 15 20	6.0 5.0 4.2	>2600 1580 900			Nose fragment Nose fragment Base fragment
34 34	60 60	2627 2627		3.5 18.6	23 23	3.2 3.2	<800 <800	NA NA	NA NA	Center fragment Base fragment
35 35	70 70	2173 2173		28.5 31.8	5 5	7.6 8.4	1800 1950	NA NA	NA NA	Nose fragment Base fragment
36 36	70 70	2578 2578	_ ↓	7.9 28.6	2 9	4.6 9.5	1500 2450	NA NA	NA NA	Center fragment Nose fragment

\*Velocity estimated on basis of stack penetration by fragment-simulating projectiles striking at measured velocities.
\*Ricocheted projectiles/fragments were not recovered during behind-the-plate studies, projectiles/fragments completely penetrating the plate were not recovered during ricochet studies.

Items 15 to 23 disclose damage potential of fragments formed when caliber .30 AP M2 projectiles completely penetrate 0.25-inch-thick Ti-6Al-4V plate. Fragments recovered were smaller than was the case for fragments resulting from penetration of 0.375-inch-thick 2024-T351 plate, and their damage potential (judging by stack penetration distances) was less. Copper fragments recovered behind the Ti-6Al-4V plate after complete penetrations were fewer and smaller than in the case of 2024-T351. Penetrations at higher velocities were accompanied by some back-spalling of fragments from the titanium alloy plate (see Items 19 and 23).

At 30° obliquity the projectile failed to penetrate at a velocity corresponding to a range of 550 yards (see Item 16), but did penetrate at velocity corresponding to 300 yards (see Item 17).

At 40° cbliquity penetration occurred at velocities corresponding to a 500-yard range (see Items 20, 21). The anomalous result of Item 22 is not understood.

At obliquities of 45 degrees and higher ricochet occurred at velocities equal to or greater than those corresponding to a 500-yard range. The projectiles broke into small fragments of limited damage potential (see Item 24).

At  $50^{\circ}$  obliquity ricochet occurred over a number of increasing velocities until a limit corresponding to 275 yards was reached (see Items 25 to 29) at which penetration occurred.

At obliquities of 55 degrees and greater, ricochet (rather than penetration) occurred over the velocity spectrum to be encountered in service.

Inspection of ricochet data for Ti-6Al-4V/caliber .30 AP M2 show at 1800-fps striking velocity the average ricochet angle decreased progressively  $25^{\circ}$ ,  $15^{\circ}$ , and  $11^{\circ}$  for increasing obliquities of  $45^{\circ}$ ,  $50^{\circ}$ , and  $60^{\circ}$ , respectively. At 2200 fps average ricochet angles of  $15^{\circ}$ ,  $18^{\circ}$ , and  $5^{\circ}$  were realized for obliquities of  $50^{\circ}$ ,  $55^{\circ}$ ,  $60^{\circ}$ , and  $70^{\circ}$ , respectively. At 2600 fps, average ricochet angles of  $15^{\circ}$ ,  $23^{\circ}$ , and  $5^{\circ}$  were realized for obliquities of  $55^{\circ}$ ,  $60^{\circ}$ , and  $70^{\circ}$ , respectively. At obliquities of  $50^{\circ}$ ,  $55^{\circ}$ , and  $70^{\circ}$  increased striking velocity had no effect on ricochet angle; at  $60^{\circ}$ , however, this was not the case.

It should be remarked that, whereas the above discussion refers to "average" ricochet angles of projectiles fragments, this so-called average applies only to those steel fragments which were recovered and recorded. Generally, fragments less than several grains in weight were not recorded. Observation of the fragment pattern on the stacked panel (see Figure 3) showed that many small fragments fanned out from the point of impact closely parallel to the plate surface. The larger steel fragments, which were recovered and recorded for assessment of damage potential, ricocheted at greater angles to the plate. In no instance did the angle of ricochet (reflection) equal the angle of incidence (90° minus angle of obliquity), however.

Whereas ricochet angle has been reported within a plane defined by the original trajectory and a line perpendicular to the plate surface, some lateral deviation from this plane was observed. For the larger steel fragments recorded the angle of such deviation was no more than several degrees. Copper fragments from the jacket deviated laterally more than the larger steel fragments.

Since some differences in penetration and ricochet behavior depended on plate material, comparison of potential for secondary damage by fragments was undertaken through analysis of 2024-T351 and Ti-6Al-4V data. Because similar obliquity/velocity combinations were lacking, comparison of damage potential of fragments after plate penetration was not possible. (However, as noted previously, weights of individual steel fragments recovered after complete penetration of 0.375-inchthick 2024-T351 plate were greater than those recovered after complete penetration

of 0.25-inch-thick Ti-6A1-4V plate.) Several sets of similar data were available for comparison of ricocheted fragment damage potential (see Table 3). Within a given set, dragments of equivalent weight usually penetrated like distances, but more heavier fragments were recovered after ricochet from 2024-T351.

Secondary Damage by Tragrants

ă†

The dencent of secondary damage requires some examination. Since vulnerability of various inspecifical aircraft components is involved, one may only project ways whereby fragments could inflict damage.

Fragments may penetrate instruments and other software rendering the device inoperable. Fragments may completely or partially sever small structural elements (e.g., vires, cables, stringer, etc.).

Table 3. DAMAGE POTENTIAL # 9100CHETED FRAGMENTS: EFFECT OF FLATE MATERIAL

		LIIL.	1 0, 75,75	ATENTAL	
it Ti*	ea Alt	: alty (degrees)	Velocity (fps)	Fragment Weight (grains)	Penetration <sup>‡</sup> Distance (inches)
	6	50	1799	36.2	5.3
	6	50	1799	43.1	5.8
25		50	1776	4.1	4.0
?		50	1776	9.3	4.2
25		50	1776	59.5	2.7
26		ან	1802	18.5	6.6
26		50	1802	39.0	6.2
	10	60	1815	6.6	7.9
	10	60	1815	27.6	7.9
	10	60	1815	31.6	7.2
	11	60	1825	36.4	7.2
32		60	1795	26.5	7.9
33		60	1820	23.9	6.9
	12	60	2208	31.3	7.8
	12	60	2208	47.5	7.1
34		60	2202	3.7	6.0
34		60	2202	8.2	5.0
34		60	2202	33.0	4.2
	13	60	2632	23.0	6.2
	13	60	2632	31.4	8.4
35		60	2627	3.5	3.2
35		60	2627	18.6	3.2
	14	70	2632	7.0	8.4
	14	70	2632	29.2	9.0
	14	70	2632	36.5	9.6
37		70	2578	7.9	4.6
37		70	2578	28.6	9.5

<sup>\*0.25-</sup>inch-thick Ti-6Al-4V plate +0.375-inch-thick 2024-T351 plate

<sup>†</sup>Penetration into stacked panel board

Sections of more massive elements may be partially penetrated. In some instances, the mechanical defect in combination with service loads may cause immediate failure or promote fatigue failure at some later time. At a given ricochet (or post-penetration) velocity, a heavier fragment will make a more serious defect because (1) it is larger, and (2) unless ricocheting itself, it will penetrate further.

4

Perforation of tubes, sumps, tanks, etc., is another means for secondary damage. At a given velocity, larger fragments have a greater chance for complete penetration and, by making a larger hole, will expedite depletion of the stored liquid or gas. These effects may involve engine operations and/or fire hazard. The ability of fragments to perforate (completely penetrate) various thicknesses of structural metals and fiber-reinforced plastic can be judged, if one assumes they behave as do fragment-simulating projectiles for which a body of data has been published (see Appendix). The assumption is considered reasonable for instances where fragments possess density, shape, and deformability approximating that of FSP's. On the basis of such assumption it is evident that fragments of caliber .30 AP M2 projectiles, either ricocheted or post-penetration, commonly possess secondary damage potential such that they will be capable of penetrating completely a 0.10-inch-thick sheet of Ti-6A1-4V, a 0.20-inch-thick panel of glass-fiber-reinforced plastic (GFRP), or 0.25-inch-thick plate of 2024-T4 (see Table 1 and Figure 4).

This study of ricochet and post-peretration fragments from caliber .30 AP M2 projectiles provides the aircraft designer with information bearing upon materials selection, modes of construction, and component disposition within the aircraft.




Figure 4. Comparison of materials penetration by FSP's at equivalent velocities.

Harder structural materials (e.g., steel and titanium alloys) promote greater fragmentation of impinging steel armor-piercing cores than do softer materials (aluminum alloys, GFRP). Since at a given velocity smaller fragments individually possess lower damage potentials, the designer may elect to promote fragmentation and provide adequate tolerance in surrounding components/structure; or, conversely, he may suppress fragmentation in order to reduce the number of secondary targets which will be struck.

Terminal Ballistics of 7.62-MM Ball M59 Projectiles Impacting Obliquely

If projectiles ricochet without fragmenting, their damage potentials are greater corresponding to their weight (see Table 4). The 7.62-mm ball M59 projectile consists of a soft 55-grain steel core within a copper jacket. When this projectile ricocheted from 0.375-inch-thick 2024-T351 plate, the core deformed to a banana shape (see Figure 5), but did not shatter. When impacting at 50 to 60° obliquity, this projectile ricocheted at low angles. As striking velocity increased, the projectile dug deeper into the plate and then ricocheted at reduced velocity. Item 43 records an instance where the projectile ricocheted from the forward face of the plate while its impact ejected an aluminum plug from the rear face, leaving a sizeable hole.

When the 7.62-mm ball M59 projectile struck Ti-6A1-4V plate at obliquity of 50 to 60°, there was no penetration or observable plate deformation over the range of velocities to be encountered in service. At points of impact the plate surface was smeared with copper and iron, the appearance at low magnification suggesting that instantaneous melting had occurred. The projectile cores were flattened on one side with a banana curvature (see Figure 5). It was observed that the weight of cores recovered from projectiles impacting at 50 degree; was reduced several tenths of a grain, presumably from erosion/alloying during impact. Since molten metal seems to have been formed and ejected, possibility of incendiary action is postulated.

Again, a low order of ricochet angle was observed for both plate materials and both obliquities.

Table 4. TERMINAL BALLISTICS OF 7.62-MM BALL M59 PROJECTILES VERSUS Ti-6A1-4V AND 2024-T351 PLATES\*

Item		Obliquity (degrees)	Velocity (fps)	Extent of Plate Penetration	Fragment Weightt (grains)	Angle of Ricochet (degrees)	Ricochet Stack Penetration (inches)	Remarks
0.375-inch-thick	40	50	1842	Partial	53.6	5	6.2	
2024-T351 plate	41	60	1847	Partial	53.6	8	8.9	
	42	60	2196	Partial	53 6	5	8.1	
	43	60	2585	Complete	53.6	5	6.8	Projectile ricocheted, plug ejected from rear face of plate
0.25-inch-thick	44	50	1704	Partial	53.2	5	9.8	,
Ti-6Al-4V plate	45	50	1794	í	53.1	13	10.1	
	46	50	2223	]	53.4	10	10.9	
	47	60	1830	ľ	53.5	8	11.5	
	48	60	2223	]	53.6	6	11.7	
	49	60	2623	<b>†</b>	53.7	6	13.1+	Projectile would have passed through stack but was blocked at rear face

\*0.25-inch-thick annealed Ti-6Al-4V (5.76 psf) and 0.375-inch-thick 2024-T351 (5.4 psf). +Soft steel cores of M69 projectiles distorted on impact, but remained intact.




Figure 5. Steel cores from 7.62-mm ball M59 projectile, bent by ricochet from 2024-T351 aluminum plate (!eft), bent and flattened by ricochet from Ti-6Al- 4V plate (right).

19-066-364/AMC-76

Attempts to estimate core ricochet velocities on the basis of FSP penetration data resulted in anomalously high values which were attributed to the difference in shape between the deformed cores and the FSP's.

Comparing damage potential (stacked panel penetration) of ricocheted 7.62-mm ball M59 cores as a function of target plate material, plate impact velocity and obliquity reveals significant differences (see Figure 6). Damage potential of ricocheted cores from projectiles striking 0.375-inch-thick 2024-T351 plate at 60° obliquity decreased with impact velocity, whereas the damage potential of cores ricocheted from like projectiles striking 0.25-inch-thick Ti-6A1-4V plate at 50° and 60° obliquities increased with impact velocity. The reason for this difference is apparent when plate penetration of the two materials is compared: the aluminum alloy plate sustained greater damage as impact velocity increased, but absorbed more of the projectile's energy; by contrast, the titanium alloy plate was neither penetrated nor deformed by projectile impact and higher impact velocities translated unreduced to higher ricochet velocities, i.e., greater damage potential of the ricocheted core. Examination of stack penetration distances for comparable items (41 versus 47, 42 versus 48, 43 versus 49) indicates that damage potentials of cores ricocheted from the Ti-6Al-4V plate exceeded those of cores ricocheted from 2024-T351 by 29 to 93+ percent.

The above observations and findings have several connotations for aircraft design. Structural elements fashioned from Ti-6Al-4V with sections 0.25 inch thick or greater will not be damaged by 7.62-mm ball M59 projectiles striking under service conditions which result in ricochet, whereas elements fashioned from 2024-T351 with sections 0.375 inch thick or greater will be deformed and/or partially penetrated.

If structural elements fashioned from 2024-T351 can tolerate the damage imparted by 7.62-mm ball M59 projectiles striking at obliquity (i.e., the structure or component remains functional), cores ricocheting from such structural elements will possess substantially less potential for inflicting secondary damage than would be the case if the structural elements were fashioned of Ti-6Al-4V. This behavior should also be considered in armor applications where secondary damage to adjoining personnel/structure by ricocheted ball projectiles is a factor.




Figure 6. Effect of target material, impact velocity and obliquity on damage potential of ricocheted cores from 7.62-mm ball M59 projectiles.

If steel fragments from high explosive shell and SAM warheads ricochet at lower velocities from aluminum than from titanium structure (as would be expected on the basis of 7.62-mm ball M59 core ricochet data), materials selection will also influence vulnerability of aircraft structure and components to secondary damage from fragmenting threats.

#### Aircraft Design for Reduced Vulnerability

For like conditions of impact velocity and obliquity, cores of 7.62-mm ball M59 projectile ricochet intact and possess higher potentials for secondary damage than do ricocheting fragments of cores from caliber .30 AP M2 projectiles, fragments which, on the average, weigh considerably less than the intact core. However, on a per-round basis, a greater number of secondary targets is likely to be struck by the fragments. If a secondary target is soft, a fragment's damage potential may suffice to render it inoperative. Aircraft designers not infrequently surround critical components with less vital parts in order to reduce the likelihood that the former will be struck by threat projectiles. This stratagem may not work, if the critical component remains vulnerable to ricocheted or post-penetration cores or fragments.

If a system will be exposed to a projectile threat only from a certain direction, designers may use this circumstance to advantage. There has, for example, been no requirement to protect helicopters from small arms fire originating from above. Similarly, if the direction of incident fire is known, or can be restricted (as by shielding), it may be possible to design and position a component in such a way as to maximize ballistic tolerance without suffering a weight/performance penalty. Housings, for example, could be constructed of materials which resist penetration, and with surfaces inclined so that the preponderance of incident

small arms projectiles would strike at obliquity and ricochet. (To provide such tolerance for a multidirectional threat would require heavier wall sections and impose some weight penalty.) Continuing this line of reasoning, if both threat direction and obliquity of impact are known, ricochet of fragments can be predicted and appropriate measures taken to relocate or protect soft parts susceptible to secondary damage.

#### **CONCLUSIONS**

- 1. When caliber .30 AP M2 projectiles struck 0.375-inch-thick 2024-T351 plate at velocities corresponding to 500 yards range or less, and at test obliquities of 30 to 70°, the hardened steel core broke, whether in ricochet or during penetration, so that two large fragments remained, comprising most of the core weight. In both the ricochet or post-penetration modes these steel fragments possessed potential for substantial secondary damage. During complete penetration a plug of aluminum was ejected from the rear surface of the plate and copper fragments from the jacket carried through with the core.
- 2. When caliber .30 AP M2 projectiles struck 0.25-inch-thick Ti-6A1-4V plate under similar test conditions to the above, core breakage again occurred and the extent of fragmentation was greater, i.e., a larger number of smaller fragments was generated, but some larger fragments remained. Relatively few jacket fragments passed through the plate during complete penetration. Back-spall commonly occurred during complete penetrations.
- 3. For ricocheted fragments generated under similar test conditions of velocity and obliquity of impact, those of like weight penetrated stacked panel material to roughly equivalent distances. Penetration distance was taken to be a measure of damage potential. Using fragment-simulating projectiles fired directly into a stacked panel at 0° obliquity, a correlation between penetration distance and striking velocity was established. Assuming similar penetration behavior for core fragments from caliber .30 AP M2 projectiles, damage potential of fragments was rated in terms of ability to penetrate completely various thicknesses of 2024-T4 plate, Ti-6A1-4V sheet, and glass-fiber-reinforced plastic.
- 4. Selection of materials for those components directly exposed to incident fire can affect fragmentation of armor-piercing cores. Materials which promote fragmentation result in more but smaller fragments, the individual damage potencial of which is less than that of larger fragments, assuming like velocities. In circumstances where the vulnerable area of soft parts exposed to ricochet is small, materials which favor a minimum number of fragments may be preferred in order to reduce probability of a hit.
- 5. The angle of ricochet for fragments of caliber .30 AP M2 projectiles was shown to be appreciably less than the angle of incidence (90° minus angle of obliquity). Small fragments fanned out from the point of impact close to the plate surface, while larger fragments resocheted at somewhat greater angles. Angles of fragment ricochet were least at the lighest obliquity, 70 degrees. Lateral deviation a larger fragments from the plainal trajectory was only a few degrees.

- 6. When 7.62-mm ball M59 projectiles struck 0.375-inch-thick 2024-T351 and 0.25-inch-thick Ti-6Al-4V plate at velocities corresponding to 500 yards range or less, the soft steel cores deformed but did not fragment. As striking velocity increased, the aluminum alloy plate was indented more severely and damage potential of the ricocheted core decreased. The Ti-6Al-4V plate was neither deformed nor indented by these cores. The damage potential of M59 cores ricocheting from the titanium plate increased both with striking velocity and with obliquity. This behavior indicates an inverse relation of primary to secondary damage where ricochet of soft steel projectile cores is concerned. This relation may also apply to steel fragments from high explosive shell/warheads. A degree of control as regards this inverse relation can be achieved through selection of structural materials.
- 7. Options for reducing aircraft vulnerability to secondary damage from ricocheted projectile cores and fragments include design and positioning of components. Under circumstances where ricochet trajectories are limited, the designer has the choice of (1) designing the component to defeat the ricochet or tolerate such damage as it may inflict; otherwise, (2) he may elect to position the component in a less hazardous location.

#### **ACKNOWLEDGMENT**

This will express the authors' gratitude to personnel of Ballistic Test Range for their ready cooperation during conduct of the subject investigation, in particular to Mr. Salvatore Favuzza whose interest and technical assistance were most helpful.

#### APPENDIX. STACK PENETRATION BY FRAGMENT-SIMULATING PROJECTILES

The damage potential of fragments from high-explosive ammunition has long been a matter of concern to designers of weapon systems. Such fragments vary over a wide range of weight and shape depending upon the shell, bomb, or other device from which they derive. Certain munitions have been developed to release fragments of a weight optimal for antipersonnel use. Studies, both to determine optimal antipersonnel fragment weight and, conversely, to evaluate personnel armor providing protection against such fragments, have been facilitated through use of fragmentsimulating projectiles (FSP) which can be fired under reproducible test conditions against selected targets.

One design of FSP extensively used in personnel armor development at AMMRC is shown in Figure A-1. This design was adopted in the subject program. It is produced in a number of standard weights over the range 1.35 to 830 grains. The smaller simulators, 1.35, 2.65, and 5.85 grains, are mounted singly in plastic sabots and fired from a caliber .22 gun. All others are fired (without sabots) from standard rifled gun tubes: e.g., 17 gr/cal. .22, 44 gr/cal. .30, etc. These FSP's are fashioned from steel heat treated to Rockwell C 30  $\pm$  2 hardness (which is the average hardness of fragments recovered from domestic 105-mm HE shell).

In the subject program penetration of stacked panel sections by 5.85-, 17-, and 44-grain FSP's fired over a range of velocities was used to assess the ballistic behavior of the panel material (see page 2 of the report). Stack penetration data for selected FSP's are listed in Table A-1 and plotted as a function of striking velocity in Figure A-2. Using interpolated values from Figure A-2, curves relating stacked panel penetration and fragment weight at 200 fps velocity intervals over the range 800 to 2600 fps were constructed, see Figure A-3. Using curves in Figure A-3 and curves depicting FSP behavior against various materials previously published, it was possible to equate (a) stacked panel penetration with (b) material thickness completely penetrated for several weights of FSP striking at equivalent velocities (see Figure 4 in body of this report).




Figure A-1. Fragment-simulating projectile, 17 grain/caliber .22.

Table A-1. STACK PENETRATION BY FRAGMENT-SIMULATING PROJECTILES\*

Projectile Weight (grains)	Velocity (fps)	Penetration (inches)
5.85	631 1029 1542 1941 2336 2661	2.0 3.2 4.6 5.2 5.8 6.2
17.0	490 1163 1531 1906	2.0 4.6 5.2 6.8
44.0	682 782 1170 1197 1235 1332 1332	3.2 3.9 6.2 6.2 6.8 6.8

<sup>\*</sup>For design of these FSP's, see Figure A-1.




Figure A-2. Penetration of FSP's into stacked panels as a function of velocity.




Figure A-3. Curves for estimating striking velocity of FSP on basis of penetration into stacked panels.

ş|.-

```
No. of
Copies
Copies
                                                                                                                                                                                                                    Tο
        Office of the Director, Defense Research and Engineering, The Pentagon, Washington, D. C. 20301
                                                                                                                                                            National Aeronautics and Space Administration.
                                                                                                                                                           Washington, D. C. 20546
ATTN: Mr. B. G. Achhammer
Mr. G. L. Deutsch - Code RR-1
 12 Commander, Defense Documentation Center, Cameron Station,
Building 5, 5010 Duke Street, Alexandria, Virginia 22314
                                                                                                                                                           National Aeronautics and Space Administration, Marshall
Space Flight Center, Huntsville, Alabama 35812
ATTM: R-P&VE-M, R. J. Schwinghamer
S&E-ME-MM, Mr. W. A. Wilson, Building 4720
   Metals and Ceramics Information Center, Battelle Columbus
Laboratories, 505 King Avenue, Columbus, Ohio 43201
1 ATTN: J. H. Brown, Jr.
                                                                                                                                                          Aeronautical Systems Division (AFSC) Wright-Patterson
Air Force Base, Ohio 45433
ATTN: ASE/ENFEF, D. C. Wight
ASD/ENFTV, LT COL J. N. McCready
ASD/ENFTV, D. J. Wa'lick
ASD/XRHD, G. B. Bennett
ASD/XRHD, S. E. Tate
   Chief of Research and Development, Department of the Army, Washington, D. C. 20310
2 ATTN: Physical and Engineering Sciences Division
   Commander, Army Research Office, P. O. Box 12211, Research
Triangle Park, North Carolina 27709
1 ATTN: Information Processing Office
        Commander, U. S. Army Materiel Development and Readiness
Command, 5001 Eisenhower Avenue, Alexandría,
Virginia 22333
ATTN. DRCDE-TC
                                                                                                                                                     Aerospace Medical Research Laboratories, Wright-Patterson
Air Force Base, Ohio 45433
1 ATTN: AMRL/EMT, C. N. Day
                       DRCDE-L, Light Armor Coordination Office
DRCSA-S, Dr. R. B. Dillaway, Chief Scientist
                                                                                                                                                     Air Force Armament Laboratory, Eglin Air Force Base,
Florida 32542
1 ATTN: AFATL/DLYA, V. D. Thornton
        Commander, U. S. Army Electronics Command, Fort Monmouth,
New Jersey 07703
ATTN: DRSEL-GG-DD
DRSEL-GG-DM
                                                                                                                                                            Air Force Flight Dynamics Laboratory, Wright-Patterson
                                                                                                                                                          Air Force Base, Ohio 45433
ATTN: AFFDL/FES, G. W. Ducker
AFFDL/FES, C. W. Harris
AFFDL/FES, J. Hodges
AFFDL/FES, MAJ J. W. Mansur
AFFDL/TST, Library
        Commander, U. S. Army Missile Command, Redstone Arsenal,
Alabama 35809
ATTN: Technical Library
DRSMI-RSM, Mr. E. J. Wheelahan
DRSMI-CS, R. B. Clem
                                                                                                                                                    Air Force Test and Evaluation Center, Kirtland Air Force
Bass, New Mexico 87115
1 ATTN: AFTEC-JT, MAJ Palmer
  Commander, U. S. Army Armament Command, Rock Island,
Illinois 61201
2 ATTN: Technical Library
                                                                                                                                                          Armament Development and Test Center, Eglin Air Force
Base, Florida 32542
ATTN: ADTC/TS, M. H. Forbragd
        Commander, U. S. Army Tank-Automotive Research and Development Command, Warren, Hichigan 48090
                                                                                                                                                          Army Air Mobility R&D Laboratory, Eustis Directorate,
Fort Eustis, Virginia 23604
ATTN: SAVDL-EU-MOS, J. T. Robinson
SAVDL-EU-TAP
        ATTN: DRDTA-R
                      DRDTA, Research Library Branch
        Commander, Frankford Arsenal, Philadelphia,
       Pennsylvania 19137
ATTN: SARFA-L300, Mr. J. Corrie
                                                                                                                                                          Army Aviation Systems Command, P. O. Box 209,
St. Louis, Missouri 63166
ATIN: DRCPM-ASE, J. Keaton
DRCPM-ASH, R. J. Braun
DRSAV-EI, CAPT W. D. Wolfinger
DRSAV-EXH, J. C. Butler
      Commander, U. S. Army Foreign Science and Technology
Center, 220 7th Street, N. E., Charlottesville,
Yirginia 22901
ATTN: DRXST-SD2
 Librarian, U. S. Army Aviation School Library, Fort
Rucker, Alabama 36360
1 ATIN: Building 5907
                                                                                                                                                           Army Ballistic Research Laboratories, Aberdeen Proving
                                                                                                                                                          Army Bailistic Research Laborate
Ground, Maryland 21005
ATTN: DRXBR-TB, J. T. Frasier
DRXBR-VL, R. G. Bernier
DRXBR-VL, A. J. Hoffman
DRXBR-VL, R. Mayerhofer
DRXBR-VL, W. S. Thompson
       Naval Research Laboratory, Washington, D. C. 20375
ATTN: Dr. J. M. Krafft - Code 8430
Code 2627
        Chief of Naval Research, Arlington, Virginia 22217
                                                                                                                                                    Army Materiel Systems Analysis Activity, Aberdeen Proving Ground, Maryland 21005
1 ATTN: DRXSY-AA, Director
       ATTN: Code 471
Code 474, N. Perrone
       Air Force Materials Laboratory, Wright-Patterson
Air Force Base, Ohio 45433
ATIN: AFML/MXE/E. Morrissey
                                                                                                                                                    Chief of Naval Operations, Washington D. C. 20350
1 ATTN: OP-987, Director
                      AFML/LC
                                                                                                                                                    Department of Transportation - FAA, 2100 Second Street, S.W., Rm 1400C, Washington, D. C. 20591
1 ATTN: ARD-520, R. A. Kirsch
                      AFML/LLP/D. M. Forney, Jr.
AFML/MBC/Mr. Stanley Schulman
AFML/MXE/A. Olevitch
```

No. of No. of Copies Copies To Deputy Chief of Staff (AIR), Marine Corps Headquarters, Washington, D. C. 20380 ATTN: AAW-61, LT COL F. C. Regan David W. Taylor, Naval Ship R&D Center, Bethesda, Maryland 20084 ATTN: Code 1740.2, F. J. Fisch Code 1740.2, O. F. Hackett FAA/NAFEC, Alantic City, New Jersey 08405 ATTN: ANA-430, L. J. Garodz ANA-64, NAFEC Library Naval Surface Weapons Center, Dahlgren Laboratory, Dahlgren, Virginia 22448
ATTN: DG-10, T. L. Wasmund
DG-34, W. A. Mannschrect
DK-23, B. W. Montrief Foreign Technology Division (AFSC), Wright-Patterson Air Force Base, Ohio 45433 Library, A. D. Hopkins ATTN: FTD/NICD Marine Corps Development Center, Quantico, Virginia 21134 ATTN: D-091, LT COI J. Givan Naval Weapons Center, China Lake, California 93555 ATTN: Code 40701, M. H. Keith Code 408, H. Drake NASA - Ames Research Center, Mail Stop 223-6, Moffett Field, California 94035 1 ATTN. SC. J. Parker Commander, Picatinny Arsenal, Dover, New Jersey 07801 1 ATTN: SARPA-AD-C, S. K. Einbinder NASA - Ames Research Center, Army Air Mobility R&D Laboratory, Mail Stop 207-5, Moffett Field, California 94035 Commander, Rock Island Arsenal, Rock Island, Illinois 61201 1 ATTN: DRSAR-PPV, D. K. Kotecki 1 ATTN: SAVDL-AS-X, F. H. Immen Aeroquip Corporation, Subsidiary of Libbey-Owens Ford Company, 300 S. East Avenue, Jackson, Michigan 49203 1 ATTN: E. R. Steinert NASA - Johnson Spacecraft Center, Houston, Texas 77058 ATTN: JM6 ES-5, F. S. Dawn Armament Systems, Inc., 712-F North Valley, Anaheim, California 92801 1 ATTN: J. Musch NASA - Lewis Research Center, 21000 Brookpark Road, Mail Stop 500-202, Cleveland, Ohio 44135 ATTN: Library, D. Morris Beech Aircraft Corporation, 9709 E. Central Avenue, Wichita, Kansas 67201 ATTN: Engineering Library, T. R. Hales R. J. Wood National Bureau of Standards, Building 225, Rm. A62, Washington, D. C. 20234 ATTN: I. A. Benjamin Naval Air Development Center, Warminster, Pennsylvania 18974
ATTN: Code 063, MAD W. Boeck
Code 30P72, F. F. Borriello
Code 303, E. J. McQuillen
Code 3033, S. L. Huang
Code 5422, R. H. Beliveau
Code 5422, M. C. Mitchell
Code 5423, B. L. Cavallo Bell Helicopter Company, A Textron Company, P. O. Box 482, Fort North, Texas 76101 1 ATTN: J. R. Johnson Boeing Vertol Company, A Division of The Boeing Company, P. O. Box 16858, Philadelphia, Pennsylvania 19142 ATTN: J. E. Gonsalves, M/S P32-19 Calspan Corporation, P. O. Box 235, Buffalo, New York 14221 ATTN: Library, V. M. Young Nava: Air Propulsion Test Center, Trenton, New Jersey 08628 1 ATTN: PE3A, J. Mendrala CDI Corporation, M & T Company, 2130 Arch Street, Philadelphia, Pennsylvania 19103
1 ATTN: E. P. Lorge Naval Air Systems Command, Washington, D. C. 20361 AITN: AIR-03PAF, CDR R. C. Gibson AIR 5203, R. Schmidt AIR-5204J, LT COL R. T. Reners AIR-530313, R. D. Hume Cossna Aircraft Company, Wallace Division, P. O. Box 1977, Wichita, Kansas 67201 AITN: B. B. Overfield AIR-531 AIR-5323 AIR-5363 E-Systems Inc., Greenville Division, P. O. Box 1056, Greenville, Texas 75401 1 ATIN: Librarian, J. Moore Naval Material Command, Washington, D. C. 20360 ATTN: MAT-0331, H. G. Moore Fairchild Industries, Inc., Fairchild Republic Company, Conklin Street, Farmingdale, Long Island, New York 11735 1 ATTN: Engineering Library, G. A. Mauter Maval Ordnance Station, Indian Head, Maryland 20640 ATTN: Code 5123F, D. H. Brooks Falcon Research and Development Company, 696 Fairmount Avenue, Baltimore, Maryland 21204 1 ATTN: W. J Douglass, Jr. Naval Post Graduate School, Monterey, California 93946 ATTN: Code 578P, R. E. Ball Naval Sea Systems Command, Washington, D. C. 20362 ATIN: SEA-03511, C. H. Pohler Falcon Research and Development Company, 601 San Pedro, N.E., Suite 205, Albuquerque, New Mexico 87108 Haval Ship Engineering Center, Hyattsville, Maryland 20782 ATTN: Code 61050 1 ATTN: W. L. Baker Naval Ship R&D Center, Annapolis, Maryland 21402 ATTN: Code 2831, R. W. McQuaid Code 2851, R. O. Foernsler Code 2851, J. R. Lugar General Dynamics Corporation, Convair Division, P. O. Box 80877, San Diego, California 92138 1 AIIN: Research Library, U. J. Sweeney

\$ 10

General Dynamics Corporation, Fort Worth Division, Grants Lane, P. O. Box 748, Fort Worth, Texas 76101 ATTR: P. R. deTonnancour/G. W. Bower.

General Research Corporation, Science and Technology Division, 5383 Hollister Avenue, P. O. Box 3587, Santa Barbara, California 93105 1 ATTN: R. Rodman

Goodyear Aerospace Corporation, 1210 Massillon Road, Akron, Ohio 44315 1 ATTN: J. R. Wolfersberger, D/152G

Grumman Aerospace Corporation, South Oyster Bay Road, dethpage, New York 11714 1 ATTN: Technical Information Center, J. Davis

Hughes Helicopters, A Division of Summa Corporation, Centinela & Teale Street, Culver City, California 90230 1 ATTN: Library, 2/T2124, D. K. Goss

ITT Research Institute, 10 West 35th Street, Chicago, Illinois 606i6 1 ATTN: K. McKee

JG Engineering Research Associaties, 3831 Menlo Drive, Baltimore, Maryland 21215 1 ATTN: J, E. Greenspan

Kamen Aerospace Corporation, Old Winsor Road, Bloomfield, Connecticut 06002 1 ATTN: H. E. Showalter

Lockheed - California Company, A Division of Lockheed Aircraft Corporation, Burbank, California 91503 1 ATTN: Technological Information Center, 84-40, U-35, A-1

Lockheed - California Company, A Division of Lockheed Aircraft Corporation, P. O. Box 551, Burbank, California 91520 1 ATTN: C. W. Cook

Lockheed - Georgia Compan, A Division of Lockheed Aircraft Corporation, 86 S. Cobb Drive, Marietta, Georgia 30063 1 ATTN: C. K. Bauer

LTV Aerospace Corporation, Youtht Systems Division, P. O. Box 5907, Dallas, Texas 75222 1 ATTN: G. Gilder, Jr.

Martin-Marietta Corporation, Orlando Division, P. O. Box 5837, Orlando, Florida 32805 1 ATTN: Library, M. C. Griffith

McDonnell Aircraft Company, McDonnell Douglas Corporation, P. O. Box 516, St. Louis, Missouri 63166 1 ATTN: Library

McDonnell Douglas Corporation, 3855 Lakewood Boulevard, Long Blach, California 90846 1 ATTN: Technical Library, Cl 290/36-84

No. of Copies To

Northrop Corporation, Aircraft Division, 3901 W. Broadway, Hawthorne, California 90250 1 ATTN: Mgr. Library Services, H. W. Jones

Northrop Corporation, Ventura Division, 1515 Rancho Conejo Boulevard, Newbury Park, California 91320 1 ATTN: M. Raine

PRC Technical Applications, Inc., 7600 Old Springhouse Road, McLean, Virginia 22101 1 ATTN: G. E. Monroe

Protective Materials Company, York Street, Andover, Massachusetts 01810 1 ATTN: M. H. Miller

Rochwell International Corporation, 4300 E. Fifth Avenue, P. O. Box 1259, Columbus, Ohio 43216 1 ATTN: Technical Information Center, D. Z. Cox

Rockwell International Corporation, Los Angeles Aircraft Division, B-I Division, International Airport, Los Angeles, California 90009 1 ATTN: W. L. Jackson

Sikorsky Aircraft, A Division of United Aircraft Corporation, Main Street, Stratford, Connecticut 06602 1 ATTN: J. B. Faulk

Teledyne CAE, 1330 Laskey Road, Toledo, Ohio 43697 1 ATTN: Librarian, M. Dowdell

Teledyne Ryan Aeronautical, 2701 Harbor Drive, San Diego, California 92112 1 ATTN: Technical Information Services, W. E. Ebner

The BDM Corporation, 1920 Aline Avenue, Vienna, Virginia 22180 1 ATTN: J. W. Milanski

The Boeing Company, Wichita Division, 3801 S. Oliver Street, Wichita, Kansas 67210 1 ATTN: Library

The Boeing Company, Aerospace Corporation, P. O. Box 3999, Seattle, Washington 98124 1 ATIN: R. G. Blaisdell, M/S 8C-42

Uniroyal, Inc., Mishawaka Plant, 407 N. Main Street, Mishawaka, Indiana 46544 1 ATTN: J. D. Galloway

Uniroyal, Inc., Government Affairs, 1700 K. Street, N.W. Washington, D. C. 20006 1 ATTN: D. Gillett

Director, Army Materials and Mechanics Research Center, Matertown, Massachusetts 02172 ATTN: DRXMR-PL DRXMR-AG

Army Materials and Mechanics Research Center, Watertown, Massachusetts 02172 SECONDARY DAMAGE TO AIRCRAFT BY RICCHETED SHALL ARNS PROJECTILES AND FRAGNENTS - SHALL ARNS PROJECTILES AND FRAGNENTS - Stuart V. Arnold and Russell G. Hardy  Technical Report AWMRC TR 76-35, November 1976, 19 pp - Illus-tables, D/A Project 111/2105AH84, Illus-tables, D/A Project 111/2105AH84, Illus-tables, D/A Project 111/2105AH84, Inder certain conditions of oblique impact against aircraft structures, small arms  Projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber .30 AP M2 and 7.62-rm ball M59 projectiles striking 0.375-inch-thick 2024-1351 aluminum and 0.25-inch-thick I1-6Al-4V alloy plates over ranges of obliq- uity and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.	Army Materials and Mechanics Research Center,  Marertown, Massachusetts 02172 SECONDARY DAWAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAWAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAWAGE TO AIRCRAFT BY RICOCHETED STUART V. Arnold and Russell G. Hardy Stuart V. Arnold and Russell G. Hardy Technical Report AMMRC TR 76-35, November 1976, 19 pp - Aircraft vulnerability illus-tables, D/A Projcct, 11162105AH84, AMCHS Code 612105.11.H8400 Under certain conditions of oblique impact against aircraft structures, small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber. 30 AP MZ and 7.62-man ball M59 projectiles striking 0.25-incl-thick 2024-135] aluminum and 0.25-incl-thick [1-6A1-4V alloy plates over ranges of oblique inty and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.
Army Materials and Mechanics Research Center,  Watertown, Massachusetts 02172 SECONDARY DAWAGE TO AIRCAGT BY RICOCHETED SECONDARY DAWAGE TO AIRCAGT BY RICOCHETED SECONDARY DAWAGE TO AIRCAGNIS SMALL ARMS PROJECTILES AND FAGGENIS STABLL ARMS PROJECTILES AND FAGGENIS STABLL ARMS PROJECTILES AND FAGGENIS Technical Report AMPRC IR 76-35, November 1976, 19 pp - Aircraft vulnerability illus-tables, DA Project ITI62105AH84, Illus-tables, DA Project ITI62105AH84, AMCHS Code 612105.11.H8400 Under certain conditions of oblique impact against aircraft structures, small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber. 30 AP WZ and 7.62-mm ball H59 projectiles striking 0.375-inch-thick 2024-1351 aluminum and 0.25-inch-thick Ii-6Al-4V alloy plates over ranges of obliquity and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.	Army Materials and Mechanics Research Center,  Materiown, Massachusetts 02172 SECONDARY DAVAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAVAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAVAGE TO AIRCRAFT BY RICOCHETED SYALL ARMS PROJECTILES AND FRAGMENTS - STUART V. Arnold and Russell G. Hardy Technical Report APMRC TR 76-35, November 1976, 19 pp - Technical Report APMRC TR 76-35, November 1976, 19 pp - Terminal ballistics AMCMS Code 612105.11.H8400 Under certain conditions of oblique impact against aircraft structures, small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber 30 AP M2 and 7.62-mm ball M59 projectiles striking 0.375-inch-thick 2024-1751 aluminum and 0.25-inch-thick Ti-6A1-4V alloy plates over ranges of obliquity and velocity. Effects of these factors upon pocential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.

UNCLASSIFIED UNLIMITED EISTRIBUTION Key words Aircraft v.lnerability Terminal ballistics Aluminum alloys craft structures. small arms ausing damage to adjoining cribes terminal tallistics striking 0.375-inch-thick plates over ranges of obliq- ntial for secondary damage are s to reduce vulnerability to	AD  UNCLASSIFIED  UNLIMITED GISTRIBUTION  Key Words  Aircraft vulnerability Terminal ballistics Aluminum alloys  ribs terructures, smail arms using damage to adjoining ribs terminal ballistics plates over ranges of obliq- triking 0.375-inch-thick plates over ranges of obliq- tial for secondary damage are to reduce vulnerability to
Army Materials and Mechanics Research Center,  Waterfown, Massachusetts 02172 SECONDRRY DAMAGE TO ARRCARFT BY RICOCHETED SECONDRRY DAMAGE TO ARRCARFT BY RICOCHETED SECONDRRY DAMAGE TO ARRCARFT BY RICOCHETED SHALL ARMS PROJECTILES AND FRAGMENTS - Stuart V. Arnold and Russell G. Hardy  Fechnical Report AMMRC TR 76-35, November 1976, 19 pp - Aircraft v. Incraft v. Incrability illus-tables, DA Project III02105AH84, Alminum alloys Under certain conditions of oblique impact against aircraft structures. Small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal tallistics of caliber 30 AP M2 and 7.62-inch-thick Ii-6Al-4V alloy plates over ranges of obliquity and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft stru-tures to reduce vulnerability to ricochet damage are proposed.	Army Materials and Mechanics Research Center,  Materiown, Massachusetts 02172 SECONDARY DAMAGE TO AIRCAAFI BY RICOCHETED SECONDARY DAMAGE TO AIRCAAFI BY ROY WORDS STUART V. AFOOTO TO TO TO THE
UNCLASSIFIED UNLIMITED DISTRIBUTION Key Words Key Words Anroraft vulnerability Terminal ballistics Aluminum alloys anroraft structures, small arms by causing damage to adjoining describes terminal ballistics les striking 0.375-inch-thick potential for secondary damage are tures to reduce vulnerability to	AD UNCLASSIFIED  "W.! !WIED DISTRIBUTION  Key
Army Materials and Mechanics Research Center,  Waterfoam, Massachusetts  Waterfoam, Massachusetts  SECONDARY DAWAGE TO AIRCRAFT BY RICCCHETED  SECONDARY DAWAGE TO AIRCRAFT BY RICCCHETED  SMALL ARMS PROJECTILES AND FRAGMENTS -  SHALL ARMS PROJECTILES AND FRAGMENTS -  Key Words  Technical Report AMMRC TR 76-35, November 1976, 19 pp -  Terminal ballistics  AMCMS Code 612105.11.H8400  Under certain conditions of oblique impact against aircraft structures, small arms  projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining  structures, components, or personnel. This report describes terminal ballistics  of calliber .30 AP M2 and 7.62-inch-thick Ti-6d-4W alloy plates over ranges of obliquity and velocity. Effects of these factors upon potential for secondary damage are  assessed. Principles for design of aircraft structures to reduce vulnerability to  ricochet damage are proposed.	Army Haterials and Mechanics Research Center,  Materiown, Massachusetts 02172 SECONDARY DAMAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAMAGE TO AIRCRAFT BY RICOCHETED SECONDARY DAMAGE TO AIRCRAFT BY RICOCHETED SHALL ARMS PROJECTILES AND FAGMENTS Stuart V. Arnold and Russell G. Hardy Stuart V. Arnold and Russell G. Hardy Technical Report APMRC TR 76-35, November 1976, 19 pp. Aircraft vulnerability illus-tables, DAP Project 17162105AH84, ALCKS Code 612105.11.H8400 Under certain conditions of oblique impact against aircraft structures, small arms projectiles (or fragments thereof) ricochet, thereby causing damage to adjoining structures, components, or personnel. This report describes terminal ballistics of caliber 30 AP M2 and 0.26-rm ball M59 projectiles striking 0.375-inch-thick 2024-1751 aluminum and 0.26-rm ball M59 projectiles striking 0.375-inch-thick 2024-1751 aluminum and 0.25-inch-thick Ti-6Al-4V alloy plates over ranges of obliquity and velocity. Effects of these factors upon potential for secondary damage are assessed. Principles for design of aircraft structures to reduce vulnerability to ricochet damage are proposed.

and the second of the second second second

こうかん となっている これのこと ないかんない かいかいしゃん